MIMMING OF

## WORK START DATE:

## CONTRACTOR

## WORK AUTHORIZATION FORM

1. USS	2. SYSTEM		3. WAF NO.
MCFAUL (DDG-74)	SSGTG I	NTAKE #2	0271
4. JCN	5. COMPANY/ SHOP / R AIT-MARINE / KI	P/REP/PHONE / KELVIN BUIE / 757-335-1010	
7. JOB DESCRIPTION & LOCATION	6. TECHNICAL WORK 1 251-30-002		
KTR REQUEST BLOW-IN DOOR TO BE INSTALL NEW GASKET IN COMPART		PEN POSITION IN-	ORDER TO REMOVE AN
	PREPARATION FOR W	OBK	
8. POST WORK TESTING IS AS SPECIFIED: D		□ NO TEST REQD	☑ FORMAL TEST PROGRA
10. DIVISION/REPAIR ACTIVITY READY TO CO	NINENCE WORK TO DIVISION	ra KelvinBı	160,
10. DIVISION/REPAIR ACTIVITY READY TO CO	THE PROJECT CONTROL AND ADDRESS OF THE PROPERTY OF THE PARTY OF THE PA		ue DATE
11. SAFETY OF SHIP (Submarine Only):   YES	AUTHORIZATION TO WO	)RK	
RA SSO (if SPOD used) or QUALIFIED WATCH DUTY OFF		N/A	DATE N/A
12. CONCURRENCES: DATE 1/27/21	D3	TÉ	DATE
13. TAGOUT REQUIRED: YES ONO EM SYSTEMICOMPONENT IS LINED UP FOR WORK, A TAG OUT IS HUNG, VERIFIED AND SIGNED BY THE REPAIR ACTIVITY (IF REQUIRED) AND SHIP,		02[NAF-0271] TAGOUT NO	27 JAN21 (00)
		WATCH DUTYOFF	DATE 27
4. PLANT/SHIP CONDITIONS (E.G., DRAINED, DE-PRESSURIZED, DE- ENERGIZED, RESTRAINED) SET. DIVISION/RA IS AUTHORIZED TO START		WATCH DUTYOFF 9	DATE 20
WORK.	ACTIONIZED TO STANT	RA TO	DATE !
*			
NOT	IFICATION OF WORK COM	PLETION	
IS DESTRICTIONS/DECAUTIONS/DEMARKS			
15. RESTRICTIONS/PRECAUTIONS/REMARKS			
15. RESTRICTIONS/PRECAUTIONS/REMARKS  16. WORK IS COMPLETE		17. TESTING IS COM	PLETE
	DATE	17. TESTING IS COM	
16. WORK IS COMPLETE	DATE		
16. WORK IS COMPLETE			DATE

☐ CHECK IF CONTINUED ON ANOTHER SHEET

The WAF must match the SHEET 1 work and it must be on the job site.

Reference: COMUSFLTFORCOMINST 4790.3 (JFMM) REV D